

To: CN=Gregory Oberley/OU=R8/O=USEPA/C=US@EPA[]
Cc: CN=Rick Wilkin/OU=ADA/O=USEPA/C=US@EPA[]
Bcc: []
From: CN=Dominic DiGiulio/OU=ADA/O=USEPA/C=US
Sent: Tue 5/22/2012 3:21:37 PM
Subject: aerial photos for pits and blowout at Pavillion

Greg:

Do you have the aerial photos for the pits at Pavillion. We need to plot the pits on a site map. Rick does not have them. Contracts indicate that the work was completed some time ago.

Also, (b)(6) privacy (Landowner name) said that you have photographs of the blowout on his property. Could I have these as well? He said that mud was blown out of the hole during the blowout. Did the drilling rig flip? These questions are important to get an idea of the gas pressure during the blowout. I am examining gas pressures in the field as a function of time.

Dominic C. DiGiulio, Ph.D.
U.S. Environmental Protection Agency
Office of Research and Development
National Risk Management Research Laboratory
Ground Water and Ecosystem Restoration Division
919 Kerr Research Drive
Ada, Oklahoma 74820

580-436-8605 (phone)
580-436-8614 (fax)
580-583-7329 (mobile)